

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS  
NY  
11-HUD  
1-

Olana (Frederic Edwin Church House)  
State Route 9G  
Hudson  
Columbia County  
New York

HABS No. NY-5501

Documentation: 15 sheets (1969, including site plan, location map, plans,  
elevations, sections, details)  
10 exterior photographs (1969)  
19 interior photographs (1969)  
2 data pages (1983)  
1 set of field records (12 field notebooks)

Cervin Robinson, photographer June and September 1969

NY-5501-1 GENERAL VIEW, FROM SOUTHWEST  
NY-5501-2 FRONT ELEVATION, FROM SOUTHEAST  
NY-5501-3 GENERAL VIEW OF REAR SECTION OF STRUCTURE, FROM NORTH  
NY-5501-4 FRONT PART OF SIDE ELEVATION, FROM EAST  
NY-5501-5 REAR PART OF SIDE ELEVATION, FROM EAST  
NY-5501-6 DETAIL OF DECORATIVE ELEMENTS OVER MAIN DOOR, FROM SOUTHEAST  
NY-5501-7 GALLERY PORCH, FROM SOUTH  
NY-5501-8 STUDIO PORCH, FROM NORTH  
NY-5501-9 STUDIO PENTHOUSE AND STUDIO WINDOW, FROM EAST  
NY-5501-10 TOWERS, LOOKING SOUTHWEST  
NY-5501-11 COURT HALL, LOOKING NORTH FROM FRONT VESTIBULE  
NY-5501-12 COURT HALL LOOKING TOWARD THE MAIN ENTRANCE, FROM NORTHWEST  
NY-5501-13 MAIN STAIRCASE FROM COURT HALL TO SECOND FLOOR, LOOKING NORTHEAST  
NY-5501-14 DETAIL, MAIN STAIRCASE FROM COURT HALL TO SECOND FLOOR, LOOKING  
NORTH  
NY-5501-15 PARLOR AT SOUTH CORNER OF STRUCTURE, FIRST FLOOR  
NY-5501-16 SITTING ROOM AT WEST CORNER OF STRUCTURE, FIRST FLOOR

- NY-5501-17 FROM LIBRARY DOOR TOWARDS DINING ROOM, LOOKING EAST
- NY-5501-18 DINING ROOM, LOOKING NORTHEAST
- NY-5501-19 DINING ROOM, LOOKING SOUTHEAST
- NY-5501-20 DINING ROOM MANTEL AND ALCOVE, DETAIL VIEW
- NY-5501-21 FIREPLACE AND MANTEL, FIRST FLOOR
- NY-5501-22 DETAIL OF MANTEL
- NY-5501-23 PANTRY SINK IN BUTLER'S PANTRY, LOOKING EAST
- NY-5501-24 STAIR RAILING IN GALLERY, LOOKING EAST
- NY-5501-25 INTERIOR OF STUDIO, FROM SOUTH, FIRST FLOOR
- NY-5501-26 STUDIO FIREPLACE AT NORTH CORNER, FIRST FLOOR
- NY-5501-27 BATHROOM, LOCATED AT NORTHWEST CORNER OF STUDIO, LOOKING SOUTH, FIRST FLOOR
- NY-5501-28 WASHBOWL IN BATHROOM, LOCATED AT NORTHWEST CORNER OF STUDIO, FIRST FLOOR. NOTE FAUCET, WHICH TURNS ON AND OFF BY SWINGING THE SPOUT LEFT AND RIGHT
- NY-5501-29 WOOD BURNING HOT-AIR FURNACE, CENTRAL PART OF BASEMENT

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Addendum to:

OLANA

HABS No. NY-5501

(Frederick Edwin Church House)

State Route 9G

Hudson

Columbia County

New York

Photographs NY-5501-1 through NY-5501-29 were previously transmitted to the Library of Congress. This is Index to Photographs page 3.

Photographs by Perry E. Borchers of the Ohio State University, 1971.

NY-5501-30	SW CORNER--LEVEL Copy photograph of photogrammetric plate LC-HABS-GS05-B-1971-801R.
NY-5501-31	SW CORNER--LEVEL Copy photograph of photogrammetric plate LC-HABS-GS05-B-1971-802L.
NY-5501-32	EAST PORTION OF SOUTH FACADE--LEVEL Copy photograph of photogrammetric plate LC-HABS-GS05-B-1971-803L.
NY-5501-33	EAST PORTION OF SOUTH FACADE--INCLINED Copy photograph of photogrammetric plate LC-HABS-GS05-B-1971-804R.